Indicators *(Continued)*

≡D **High beam indicator**

⇦⇨ **Turn signal indicator**

(ABS) **ABS (Anti-lock Brake System) indicator**
CMX500A only
Comes on when the ignition switch is turned to
the ON position. Goes off when your speed
reaches approximately 6 mph (10 km/h).
If it comes on while riding: ⟶P.96

N **Neutral indicator**
Comes on when the transmission is in Neutral.

30