Battery overcharging (regulated voltage too high).