

rule is applicable not only during break-in but at all times.

4. Upon reaching an odometer reading of 1,000 miles, you can subject the motorcycle to full throttle operation, however, do not exceed 8,000 rpm at any time (observe RED ZONE limit on tachometer).

NOTE: Do not exceed 7,000 rpm when running the engine without a load.

■ RIDING THE MOTORCYCLE

WARNING:

1. Exhaust pipes and mufflers become very hot during operation and remain sufficiently hot to inflict burns if touched, even after shutting off the engine. Wear clothing which will completely cover the legs while riding and avoid any contact with unshielded portions of the exhaust system.
2. Do not wear loose clothing which may catch on control levers, kick starter, foot pegs, drive chain, wheels and tires.
 1. After the engine has been warmed up, the motorcycle is ready for riding.
 2. While the engine is idling, pull in the clutch lever and press the gear change pedal to shift into low gear (1st).

WARNING: Ensure that the side stand is fully retracted before riding the motorcycle. Failure to retract the stand may interfere with an attempted left turn and cause serious control problems.