


Odometer/Tripmeter Display

The display (1) shows two functions: odometer and two tripmeters.

Push the button (2) to select the “ODO” and “TRIP1”, “TRIP2” mode.

To reset the trip odometer, press and hold down key (3) while the display is in “TRIP1” or “TRIP2” mode.



- (1) Odometer/Tripmeter display
- (2) Odometer/Tripmeter select button
- (3) Reset button

