

## BREAK-IN PROCEDURE

1. Never lug the engine with excessive throttle at low engine speeds. This rule is applicable not only during break-in but at all times.
  2. Maximum continuous engine speed during the first 1,000 km (600 miles) must not exceed 5,000  $\text{min}^{-1}$  (rpm).
  3. Increase the maximum continuous engine speed by 2,000  $\text{min}^{-1}$  (rpm) between odometer readings of 1,000 and 1,600 km (600 and 1,000 miles). Do not exceed 7,000  $\text{min}^{-1}$  (rpm). Vary speeds frequently, and use full throttle for short spurts only.
  4. Upon reaching an odometer reading of 1,600 km (1,000 miles), you can subject the motorcycle to full throttle operation, however, do not exceed 9,500  $\text{min}^{-1}$  (rpm) at any time.
- 

## RODAJE

1. Nunca debe forzar la motor con excesiva aceleración en velocidades bajas. Esta regla es aplicable no sólo durante el rodaje sino todo el tiempo.
2. Durante los primeros 1.000 kilómetros, la velocidad máxima continua del motor no deberá exceder 5.000  $\text{min}^{-1}$  (r.p.m.).
3. Aumente la velocidad máxima continua del motor en 2.000  $\text{min}^{-1}$  (r.p.m.), entre lecturas del odómetro de 1.000 y 1.600 km. No exceda las 7.000  $\text{min}^{-1}$  (r.p.m.). Cambie frecuentemente las velocidades y corra a total aceleración sólo en recorridos cortos.
4. Al llegar a 1.600 km de la lectura del odómetro, puede correr la moto con aceleración total. Si embargo, ésta no debe exceder 0.500  $\text{min}^{-1}$  (r.p.m.) en ningún momento.