



# Indicators & Displays

---

To reset the tripmeter to zero, press and hold the RESET button (1) for more than 2 seconds with the display in the tripmeter A or tripmeter B mode.



(1) RESET button