

### Wear inspection:

Check the chain wear label when adjusting the chain. If the red zone (5) on the label aligns with the tip of driven sprocket teeth (6) after the chain has been adjusted to the proper slack, the chain is excessively worn and must be replaced. The proper slack is:

20 – 30 mm (0.8 – 1.2 in)


### Replacement chain:

D.I.D 50 VA7

or

RK 50HF0Z3

This motorcycle has a staked master link drive chain which requires a special tool for cutting and staking. Do not use an ordinary master link with this chain. See your Honda dealer.



(5) Red zone

(6) Tip of driven sprocket teeth