
- **1.** If the engine is cold, idle the engine for 3 to 5 minutes.
- **2.** Turn the ignition switch OFF, stop the engine and wait 2 to 3 minutes.
- **3.** Place your motorcycle in an upright position on a firm, level surface.
- **4.** Check that the oil level is between the upper and lower level marks in the oil inspection window.



Maintenance

61