

Symptom	Cause/remedy
Connected, but does not operate Apple CarPlay.	You cannot operate Apple CarPlay by the center panel switches/Interface dial while the motorcycle is in motion. Operate with the left handlebar switches or park your motorcycle in a safe place, then operate.
Some functions of Apple CarPlay is not available.	Some functions may be limited due to condition of mobile network communication.
Apple CarPlay screen is too dark/bright	Selecting [Day / Night] menu in [Vehicle setting], you can select daytime mode or nighttime mode in the navigation map or an application such as Maps (▶ P. 32), also adjust backlight brightness by [Auto dimmer meter illumination] menu in [Vehicle setting] (▶ P. 31).
The multi-function display is too dark/bright	When the ignition switch is in the ACC, [Auto Dimmer Meter Illumination] function does not work. Turn the ignition switch to ON.
	The map color tone has Day/Night color tones and it changes according to the surrounding brightness. You can select daytime mode or nighttime mode. ▶ P. 32