

Audio System Trouble

| Symptom | Cause/remedy |
|--|---|
| Audio system cannot operate. | Certain manual functions and settings are disabled or inoperable while the vehicle is in motion. You cannot select a grayed-out menu until the vehicle is stopped. |
| Set menu in [Vehicle setting] does not be reflected or inoperable. | In [Vehicle setting], certain items cannot be selected and display information is limited when the ignition switch is in ACC. The set menu will be reflected to the previous setting when the ignition switch is turned ON. |
| When turning the ignition switch OFF and ON continuously. | Since the system restart takes time, it may take time until the screen is appeared. |
| High temperature/overcurrent protection | To protect the system, some operations may be limited temporarily. The system automatically recovers after the cause is solved. |
| About Idling Stop system (GL1800D/DA Canada model) | When the Idling Stop system is activated, sound may not come out temporarily for system protection, but sound will recover automatically. |
| Radio receiver sensitivity | The sensitivity of receiver is affected by the object which interrupts a radio wave nearby the radio antenna (top of the right saddlebag). |
| Software update | The statements in this owner's manual may not match your vehicle's Audio System after performing the software update (map data update). |

If the problem continues after the above-described inspection, have your motorcycle inspected by your dealer.