


Sub-Transmission Oil

UNDER SEAT CENTER



5. If the oil level is near or below the lower level mark, add the specified oil into the oil fill cap hole, fill to the upper level mark in the dipstick. Do not over fill.
6. Reinstall the oil fill cap/dipstick and front seat.

NOTICE

Running the engine with an improper oil level can cause serious engine damage.