

# Gauges, Indicators & Displays


## Odometer/Tripmeter/ Digital Clock Display

The odometer (1) shows the total miles ridden.

Tripmeter 1 (2) and tripmeter 2 (3) show number of miles ridden since you last reset the meter.

Push the select/reset button (5) to select the “ODO”, “TRIP 1”, “TRIP 2” or clock mode.

To reset the tripmeter, push and hold the select/reset button for more than 2 seconds with the display in the “TRIP 1” or “TRIP 2” mode.



- |                 |                         |
|-----------------|-------------------------|
| (1) odometer    | (4) digital clock       |
| (2) tripmeter 1 | (5) select/reset button |
| (3) tripmeter 2 | (6) tripmeter reset     |