



Tighten the axle pinch bolt to the specified torque.
TORQUE: 18–28 N·m (1.8–2.8 kg-m, 13–20 ft-lb)



Install the speedometer cable into the speedometer gearbox and tighten the set screw.



SPEEDOMETER CABLE