


← Left turn signal indicator

⇒ right turn signal indicator



N Neutral indicator

 **ABS (Anti-lock Brake System) indicator**

CBR650FA only

Comes on when the ignition switch is turned on. Goes off when your speed reaches approximately 10 km/h (6 mph).

If it comes on while riding: → P.85

HISS indicator → P.82

- Comes on briefly when the ignition switch is turned on. Goes off if the ignition key has the correct coding.
- Flashes every 2 seconds for 24 hours when the ignition switch is turned off.