



WIRING DIAGRAM



- | | | | |
|---|--------|----|-------------|
| B | BLACK | B | BROWN |
| Y | YELLOW | D | ORANGE |
| L | BLUE | L1 | LIGHT BLUE |
| G | GREEN | L2 | LIGHT GREEN |
| R | RED | P | PINK |
| W | WHITE | G | GRAY |

0030Z-HC4-0000