


WIRING DIAGRAM

U.S. model



B	BLACK
BR	BROWN
BLU	BLUE
OR	ORANGE
GRN	GREEN
WH	WHITE
GY	GRAY

COLOR CODE CHROMATING

0030Z-HNS-6700

