

## **Tachometer**

## NOTICE

Do not operate the engine in the tachometer red zone. Excessive engine speed can adversely affect engine life.