

PGM-FI (Programmed Fuel Injection) Malfunction indicator lamp (MIL)

If the MIL indicator comes on while driving, you may have a problem with the PGM-FI electronic injection system.

Slow down and stop the motorcycle in a safe place. Re-start the motorcycle.

If the MIL indicator is still on after 5 seconds, inspect the motorcycle at your Montesa dealer as soon as possible.

