


WIRING DIAGRAM (550 · 565)



Cord color	Position	
	Bk	Y
1	IG	HL
2	E	C <sub>2</sub>
	BAT	C <sub>1</sub>
	SE	C <sub>3</sub>
	W	Gn
	Bu	Y
	Bn	Bn

Switching arrangement