

# TROUBLESHOOTING

## 1. Battery undercharging (Voltage not raised to regulated voltage).

