NOTE

- · Connect the terminals and install the sockets according to the color codes indicated on the inner case.
- · Route the sub-harness as illustration shown.

Requisite Servce

Meter removal/installation (page 16-5)

Procedure		Q'ty	Remarks	
	Disassembly Order		Assembly is in the reverse order of disassembly.	
(1)	Rear cover mounting screw	5		
(2)	Rear cover	1		
(3)	Front cover mounting screw	1	₽ 70	
(4)	Front cover	1		
(5)	Wire clamp	2		
(6)	Indicator/meter light socket	7		
(7)	Wire eyelet screw	2		
(8)	Combination meter sub-harness	1	1	
(9)	Trip meter reset knob	1	1	
(10)	Speedometer gearbox mounting screw	2		
(11)	Speedometer gearbox	1		
(12)	Speedometer mounting screw	2		
	Speedometer	1		
(14)	Tachometer mounting screw	2		
	Tachometer	1		
(16)	Meter stay mounting nut	3		
	Meter stay	1		
	Inner case	1		