

## ■ Checking the Drive Chain Wear

If the drive chain slack is excessive when the rear axle is moved to the furthest limit of adjustment, the drive chain is worn and must be replaced.

**Chain:** FSCM428H or KMC428HG

If necessary have the drive chain replaced by your dealer.